



Standard Service Program Information "A" Service

Operations:

- 1) Oil/Lube/Filter
- 2) Clean battery terminals & install anti-corrosion washers
- 3) Check & fill all fluid levels
- 4) Tighten all belts, note the wear and advise
- 5) Check all tie rod ends and advise
- 6) Check tire wear and advise, check pressure
- 7) Inspect exhaust system
- 8) Check for oil leaks in the undercarriage area
- 9) Check wear on all hoses and advise
- 10) Inspect heater valves for leaks and operation
- 11) Check all emergency lighting and operations
- 12) Check all chassis lights
- 13) Inspect cot bar operations
- 14) Check O2 system for leaks
- 15) Check heat and A/C system for operation
- 16) Visually inspect unit and advise
- 17) Road test vehicle and advise

Prices for this service:

Gas Engine V-10: \$195.76

Parts and labor. (7 quarts of oil, FL820 Motorcraft oil filter, 4 anticorrosion battery washers, plus any other fluids that are necessary).

7.3 Turbo Diesel Engine: \$235.39

Parts and labor. (16 quarts of oil, FL1995 Motorcraft filter, 4 anticorrosion battery washers, plus any other fluids that are necessary).

6.0 Turbo Diesel Engine: \$249.54

Parts and labor. (16 quarts of oil, FL2016 Motorcraft filter, 6 anticorrosion battery washers, plus any other fluids that are necessary).

**Contact the VCI Service Department to
schedule your appointment.**

1-800-394-2162



Standard Service Program Information "B" Service

Operations:

- 1) Inspect tires for wear and advise
- 2) Rotate tires
- 3) Check tire pressure
- 4) Check front end alignment and advise
- 5) Inspect brakes, note wear and advise
- 6) Check king pins and advise
- 7) Check all tie rod ends and advise
- 8) Service transmission and replace screen
- 9) Service rear differential add rear additive
- 10) Remove screen from under the attendant seat and clean condenser area
- 11) Change air filter
- 12) Change fuel filter
- 13) Check glow plug circuit and advise
- 14) Check headlight alignment
- 15) Inspect and lube rear step bumper area
- 16) Check all u joints and advise
- 17) Check steering linkage
- 18) Road test vehicle and advise

Prices for this service:

6.0 Turbo Diesel Engine: \$734.40

Parts and labor.

7.3 Turbo Diesel Engine: \$734.40

Parts and labor.

Parts included in "B" service: Fuel filter, air filter, transmission filter, transmission fluid, rear fluid and additive.

All other parts that might be required will be priced separately after approval from customer.

Contact the VCI Service Department to schedule your appointment.

1-800-394-2162